



2026



Permit Required  
Confined Space Test  
- or Visit  
[Alerteducate.com](http://Alerteducate.com)



# February



Kahoot of Permit  
Required Confined  
Space

Monday	Tuesday	Wednesday	Thursday	Friday
<p><b>2 Beating the Train</b> While waiting on a train, lights, sirens to stop next to bldg. A contractor was sick of waiting and crossed the tracks to get to the time clock.</p>	<p><b>3 Wrong Tool</b> Saw another employee using a pipe wrench as a hammer.</p>	<p><b>4 Confined Space without an Attendant</b> A contractor was inside a confined space without an attendant.</p>	<p><b>5 PPE Nearby Isn't PPE Worn</b> Co-Worker had safety glasses around his neck and not his face. Then proceeded to start cutting unistrut with a bandsaw</p>	<p><b>6 Hose on the Floor</b> Person was walking across the floor and tripped over a hose on the floor.</p>
<p><b>9 Near Miss Pinch Hazard</b> Pushing a table without looking to see if anyone is in the way. Person not looking nearly pinned another person between the tables.</p>	<p><b>10 De-Energized Doesn't mean Danger Free</b> Employee didn't have on hand protection while working inside a de-energized and locked out starter. This could have resulted in pinch or cut inside the starter.</p>	<p><b>11 False Atmosphere Reading</b> The monitor hose was not inside the confined space while contractors were working inside.</p>	<p><b>12 Dropped Material Hazard</b> Saw worker cutting material on the sawhorse but realized once the cut was done the material would drop on the ground.</p>	<p><b>13 Hot Work Near a Leak</b> Observed a leaking rubber boot on the top of beer well tank. Welding was taking place on another tank nearby. So, I shut the welder down and notified my coworker of the hazard.</p>
<p><b>16 Barricade Authority Failure</b> Had a newbie do ground spot for a hoist and he/she allowed 2 people to pass through the barricade as the load was overhead and lowering down.</p>	<p><b>17 False Safet Distance</b> Employees were welding handrail, while about 10' away were sheets of plywood, 2x4, and tote bag, no screens, no fire blanket covering anything.</p>	<p><b>18 Corbon Monoxide Hazard</b> Another contractor was running a gas power washer inside building with a hot water burner creating CO2.</p>	<p><b>19 No Traffic Control</b> Contractor was flying a piece of pipe with the tower crane over road where pedestrian traffic walks and had no ground guy to hold traffic till the load was clear.</p>	<p><b>20 Impact &amp; Vibration Hazard</b> Colleague prepping floor using a jack hammer was not wearing the appropriate gloves for the task the impact resistant shock absorb gloves!</p>
<p><b>23 Runaway Loader Hazard</b> Enloader operator parked his enloader by my truck. He got out and walked over to a pile, meanwhile I looked back and his enloader is rolling out into the road almost stopping by the propane storage area.</p>	<p><b>24 Incomplete Hot Work Permit</b> Stopped colleague's due to "The Hot Work Permit" filled out incomplete the fire watch section not done, flammable materials with in 20 feet! colleagues were stick welding handrails overhead sparks coming down!</p>	<p><b>25 Respiratory Hazard</b> Worker was working inside bubble, it was getting dusty. I told him to go get dust mask that stuff is fertilizer.</p>	<p><b>26 Barricade Breach</b> While all barricades were in place and door was closed with suspended rigging above waiting for load to arrive back to crane bay crew from another contractor was observed opening the door and walking throughout the barricades meanwhile stringing out hoses and moving miscellaneous equipment unaware to potential hazards above.</p>	<p><b>27 Arc Flash Exposure</b> Power Lighting Panel door cover was open exposing the breakers, this is an OSHA violation and against mfg safeguarding for arc flash events.</p>