May 2026

Submit a See Say Stop

Respiratory Test - or Visit Alerteducate.com

PPE Test - or Visit Alerteducate.com

Monday	Tuesday	Wednesday	Thursday	Friday
				1 You Won't Always See It Had propane leak in hose. Worker smelled propane, stopped work and notified supervisor.
4 it Happens Fast Employee trying to set a door stop to keep door open placed hand on the closer arm, as another employee quickly started opening the door.	**5 Close Enough Isn't Safe** Contractor was sitting on top of two pipes with a harness on but not tied off, approximately 15 feet up.!	**6 It Only Works One way** Angle grinder was being used without a face shield.	**7 More Force, Less Control** Employee was tightening bolts without gloves and was using two wrenches (double wrenching), which is not the proper method.	**8 Doesn't Look Right** Forklift mast appeared damaged. Further inspection showed stretched fork pockets and a cracked weld at the attachment point.
11 Holding the Risk EEmployee was holding a piece of pipe in his hand while grinding because he didn't have a vise.	**12 It Wasn't His Job...Until It Was** While walking by the sugar tracks, an employee noticed a worker underneath a railcar with no wheel chocks in place.	**13 Worn...But Wrong** ECo-workers was observed wearing a hard hat backwards.	**14 In the Way** While operating a forklift, a bottle rolled and ended up near/under the brake pedal, creating a potential loss of control.	**15 Still Connected** An employee was moving a mobile torch cart with the backflow meters still attached to the cylinders.
18 The Wrong One During a walkthrough, a lock was found placed on the wrong valve, leaving product still inside the decanter.	**19 Before You Step In** A client representative walked into a baghouse area while work was ongoing without wearing a harness or fall protection.	**20 Bare Hands, Sharp Edges** Electricians were observed stripping wire without proper gloves, using bare hands.	**21 It'll Hold....Until It Doesn't** An extension ladder was set up but not secured, and no one was holding it while a worker was climbing down.	**22 Right in the Path** Employee standing in the wrong space when using a comealong.
25 You Don't Alway Notice It Employee was working alone inside a WFD area tightening bolts when the space filled with thick smoke, reducing visibility and air quality.	**26 Almost Done Isn't Done** Guy was coming down on a lift and was slowly taking off his harness before reaching the ground	**27 When You Need It, It Better Work** Eyewash station nozzle was missing its protective cover, creating a risk of contamination.	**28 It's Not Just Your Space** Cleaning concrete debris from floor above and debris falling off through grading no barricade under it.	**29 It Was Telling Him** Hole watch was not paying attention to the monitor, even though it was flashing red.