

2026 March



Submit a See Say Stop



Scaffold Test - or Visit Alerteducate.com



Kahoot of Ladder & Scaffold Safety



Ladder Test - or Visit Alerteducate.com

Monday	Tuesday	Wednesday	Thursday	Friday
<p>2 Nail Gun Missing Spring</p> <p>Missing spring in the nail gun which can cause it to miss fire.</p>	<p>3 Carrying Heavy Equipment Alone</p> <p>A coworker was attempting to carry a heavy piece of equipment by themselves.</p>	<p>4 Ladder Leg Not Locked</p> <p>An employee from another company climbed on a scaffold with a yellow tag without his harness.</p>	<p>5 That's Not Hearing Protection</p> <p>Contractor was working on sealing the cement floors, I saw that he was wearing ear buds and not ear plugs.</p>	<p>6 Caught in the Rebar</p> <p>Watched one of the concrete workers get his foot caught in the rebar while pouring and almost fall.</p>
<p>9 Short Sleeves, Hot Sparks</p> <p>Noticed employee was about to start welding in short sleeves.</p>	<p>10 Taped Is Not Repaired</p> <p>While doing a walk through a retractable extension cord reel was observed with tape wrapped around the cable. The tape was removed and damage to the outer jacket of the cord was found.</p>	<p>11 Ladder on a Round Surface</p> <p>While walking in plant noticed a 20-foot ladder was propped against a round tank surface, used to view the sight glass. The ladder was not tied off at the top or bottom,</p>	<p>12 Silent in Reverse</p> <p>When borrowing a customer's forklift, I noticed that the backup alarm did not work giving potential for someone to be hit.</p>	<p>13 Improper Rigging Setup</p> <p>I noticed the rigging shackles were upside down. The rigging wasn't properly centered before lifting load. Shackles were being side loaded. Unapproved lifting plates with no weight limit were being used to lift loads.</p>
<p>16 Reaching Past Stability</p> <p>As I was walking by I seen a customer's employee working off a ladder, but he was on his tippy toes trying.</p>	<p>17 It's Not Necessary</p> <p>We were tasked to unload 12,000 lbs. transformer for customer. A crane company was setting up the crane; the operator did not put crane pads under the outriggers. I asked him to scope the crane in and install the pads. He said it wasn't necessary.</p>	<p>18 Half a Barricade is No Barricade</p> <p>Employee was getting ready to climb the ladder and only one of the legs were locked in place. This could have resulted in a fall if the employee was on the ladder.</p>	<p>19 Yellow Tag Means Stop</p> <p>When doing a lockout, I noticed several of the valves in the lockout are not labeled. Valves should be labeled so everyone knows what they are locking out.</p>	<p>20 One Foot from Disaster</p> <p>A worker was 30-40 foot above another worker and dropped an 1 1/4' socket and landed a foot from them.</p>
<p>23 Half Protected Is Not Protected</p> <p>A company placed a barricade up on only one side and did not complete it, other people walked under the area unknowing that there was a danger.</p>	<p>24 Still Energized</p> <p>Heat trace was removed from pipe since the pipe was removed, but the heat trace was still hanging and hooked up. This could have resulted in a shock if someone tried to move it.</p>	<p>25 Work Above, Risk Below</p> <p>Scaffold crew was trying to erect a scaffold. Pipe Fitters came in and started welding above the area where the scaffold crew was working. Welding slag was falling from above.</p>	<p>26 Strength Isn't the Plan</p> <p>Employee attempted to move big gas tanks without a proper hoist setup. The tank could have fallen on the employee or been dropped while moving or lifting it in and out of welders.</p>	<p>27 Controlled Energy, Uncontrolled Ground</p> <p>While performing a lock out for us, the supervisor tripped over the corner of a pallet and slipped in the oil that was covering the floor. He caught himself before falling and no harm was done.</p>
<p>30 Eyes Down, Guard Down</p> <p>Worker was walking and looking at their phone and had no way to see what was in front of them.</p>	<p>31 Outside the Line</p> <p>Object fell outside of barricade from floor above. Went up to floor and let the workers know they had hard objects falling outside the barricaded area.</p>			